




**FIG. 1**

**FIG. 2**

**FIG. 3**




**FIG. 4**

3	2	1
4	•	0
5	6	7

**FIG. 5**

A' (START POINT)




**FIG. 6**

FIG. 7A




FIG. 7B




FIG. 8A

LABELING	1	2	3	1
ADDRESS	A	B	C	A

CONTOUR DATA AND  
FEATURE POINTS

FIG. 8B

LABELING	1	2	3	1
ADDRESS	A'	B'	C'	A'

NEW  
CONTOUR  
DATA


FIG. 8C

LABELING	1	2	3	1
ADDRESS	D	B'	C'	D

NEW  
FEATURE  
POINTS



FIG. 9




**FIG. 10**

FIG. 11

FIG. 11





FIG. 12




**FIG. 13**

FIG. 14





FIG. 15





**FIG. 16**



FIG. 17



**FIG. 18A**

0	1	1
0	X	1
0	1	1

**FIG. 18B**

0	0.5	1
0	X	1
0	0.5	1


**FIG. 18C**

0	0	1
0	X	1
0	0	1


**FIG. 18D**

0	0	0.5
0	X	1
0	0	0.5

**FIG. 19**



**FIG. 20**



**FIG. 21**